DETAILED DIAGNOSTIC REPORT

==========
DETAILED DIAGNOSTIC REPORT
==========

1. PROPERTY ISSUE SUMMARY
The property shows signs of moisture intrusion, dampness, and possible structural concerns.

2. AREA-WISE OBSERVATIONS
- Hall: Dampness near walls
- Bedrooms: Moisture patches
- Kitchen: Water seepage signs
- Bathroom: Leakage possibility
- External Walls: Cracks observed

3. ROOT CAUSE ANALYSIS
- Plumbing leakage
- Poor waterproofing
- Structural cracks

4. SEVERITY
Moderate to High

5. RECOMMENDATIONS
- Fix plumbing issues
- Apply waterproofing
- Seal cracks
- Regular inspection

6. ADDITIONAL NOTES
Thermal and inspection data indicate hidden moisture.

RAW STRUCTURED DATA

STRUCTURED DATA

Inspection Summary:

Inspection Form

Complete

Score
85.71%
Flagged items
1 Actions
0

Customer Name
Mobile:
Email:

Address:

Property Age (In years):
Floors:
11

Previous Structural audit done
No
Previous Repair work done
No
Inspection Date and Time:
27.09.2022 14:28 IST
Inspected By:
Krushna & Mahesh
Property Type:
Flat

Checklists / Inspection Checklists

Checklist:

Flagged items
1 flagged
WC
External wall

Impacted Areas/Rooms
Hall, Bedroom, Kitchen, Master Bedroom, Parking Area, Common bathroom

Impacted Area
Impacted Area 1

Negative side Description
Hall Skirting level Dampness
Negative side photographs

Photo 1
Photo 2
Photo 3
Photo 4
Photo 5
Photo 6

Photo 7

Positive side Description
Common Bathroom tile hollowness

Positive side photographs

Photo 8
Photo 9
Photo 10
Photo 11

Impacted Area 2

Negative side Description
Bedroom Skirting level
Dampness
Negative side photographs

Site Details

Positive side Description
Common Bathroom tile
hollowness
Positive side photographs

Photo 15
Photo 16
Photo 17
Photo 18
Photo 19

Impacted Area 3

Negative side Description
Master bedroom Skirting level
Dampness
Negative side photographs

Photo 20
Photo 21
Photo 22
Photo 23
Photo 24
Photo 25

Positive side Description

MB Bathroom tile hollowness

Positive side photographs

Photo 26
Photo 27
Photo 28
Photo 29
Photo 30

Impacted Area 4

Negative side Description
Kitchen Skirting level
Dampness
Negative side photographs

Photo 31
Photo 32

Positive side Description
Master bedroom bathroom
Positive side photographs

Photo 33
Photo 34
Photo 35
Photo 36
Photo 37

Impacted Area 5

Negative side Description
Master bedroom wall damness
Negative side photographs

Photo 38
Photo 39
Photo 40
Photo 41

Positive side Description
External wall crack and Duct
Issue

Positive side photographs

Photo 42
Photo 43
Photo 44
Photo 45
Photo 46
Photo 47

Photo 48

Impacted Area 6

Negative side Description
Parking Area seepage
Negative side photographs

Photo 49
Photo 50
Photo 51
Photo 52

Positive side Description
Common Bathroom tile
hollowness and plumbing issue

Positive side photographs

Photo 53

Photo 54
Photo 55
Photo 56
Photo 57

Impacted Area 7

Negative side Description
Common Bathroom Ceiling
Dampness

Negative side photographs

Photo 58
outlet Leakage

Positive side Description
Flat no 203 tile joint open and

Positive side photographs

Photo 59
Photo 60
Photo 61
Photo 62
Photo 63
Photo 64

Inspection Checklists
1 flagged, 84.21%

Condition of leakage at adjacent walls
Condition of leakage below WC

Leakage during:
All time
Leakage due to concealed plumbing
Yes

Leakage due to damage in Nahani trap/Brickbat coba under tile flooring

Yes

Positive Side Inputs F

Thermal Summary:
28.8 °C
23.4 °C
27/09/22
Hotspot :
28.8 °C
Coldspot :
23.4 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02380X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
1
27.4 °C
22.4 °C
27/09/22
Hotspot :
27.4 °C
Coldspot :
22.4 °C

Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02386X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
2
27 °C
22 °C
27/09/22
Hotspot :
27 °C
Coldspot :
22 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02395X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
3
25.7 °C
20.7 °C
27/09/22
Hotspot :
25.7 °C
Coldspot :
20.7 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02402X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
4
25.5 °C
20.5 °C
27/09/22
Hotspot :
25.5 °C

Coldspot :
20.5 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02403X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
5
25.8 °C
20.8 °C
27/09/22
Hotspot :
25.8 °C
Coldspot :
20.8 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02404X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
6
26.2 °C
21.2 °C
27/09/22
Hotspot :
26.2 °C
Coldspot :
21.2 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02405X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
7
26.5 °C
21.5 °C
27/09/22

Hotspot :
26.5 °C
Coldspot :
21.5 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02406X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
8
25.8 °C
20.8 °C
27/09/22
Hotspot :
25.8 °C
Coldspot :
20.8 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02392X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
9
25.9 °C
20.9 °C
27/09/22
Hotspot :
25.9 °C
Coldspot :
20.9 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02393X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
10
26 °C

21 °C
27/09/22
Hotspot :
26 °C
Coldspot :
21 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02394X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
11
26.1 °C
21.1 °C
27/09/22
Hotspot :
26.1 °C
Coldspot :
21.1 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02396X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
12
26.3 °C
21.3 °C
27/09/22
Hotspot :
26.3 °C
Coldspot :
21.3 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02397X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772

13
25.6 °C
20.6 °C
27/09/22
Hotspot :
25.6 °C
Coldspot :
20.6 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02398X.JPG
Device : GTC 400 C Professional
Serial Number : 02700034772
14
26.5 °C
21.5 °C
27/09/22
Hotspot :
26.5 °C
Coldspot :
21.5 °C
Emissivity :
0.94
Reflected temperature :
23 °C
Thermal image : RB02399X.JP