VEHICLE DAMAGE ASSESSMENT REPORT

Certified Computer Vision & Deep Learning AI Estimate

VEHICLE DETAILS

Manufacturer: Tata Motors
Model: Nexon EV
Manufacturing Year: 2023
Registration Number: MH-14-GH-9988

INSPECTION SUMMARY

Images Analyzed: 4 (360° Multi-View)
Damaged Components: 7
Minor Damage: 4 | **Moderate:** 0 | **Severe:** 3
AI Fusion Status: Multi-angle duplicates consolidated

DAMAGED COMPONENTS & REPAIR BREAKDOWN

Vehicle Part	Damage Type	Severity	Area %	Action	Parts Cost	Labor	Total
Front Bumper	Dent	Severe	41.2%	Replace	■21,390	■7,050	■28,440
Headlight (Right)	Crack	Severe	28.5%	Replace	■24,990	■3,360	■28,350
Exterior Panel	Scratch	Minor	28.5%	Paint/Repair	■5,090	■2,280	■7,370
Left Fender	Scratch	Minor	12.6%	Paint/Repair	■3,100	■1,610	■4,710
Front Door	Scratch	Minor	12.3%	Paint/Repair	■4,800	■2,300	■7,100
Rear Bumper	Dent	Severe	46.2%	Replace	■21,460	■7,190	■28,650
Exterior Panel	Scratch	Minor	28.5%	Paint/Repair	■5,090	■2,280	■7,370

Total Parts Cost: **■85,920**

Total Labor Cost: **■26,070**

ESTIMATED TOTAL REPAIR COST: **■111,990**

Estimated Range (95% CI): **■98,600 – ■127,700**

DISCLAIMER: This assessment is generated using Computer Vision (YOLOv8/11, Segmentation) and Machine Learning (XGBoost / Random Forest) predictive models. The estimated repair costs represent regional benchmark approximations and may vary based on authorized dealership quotations, OEM parts availability, and internal mechanical damages hidden beneath body panels.