HUG fingertip error after constraint-feasible seed restoration

All 30 computed tip errors satisfy their original caps; six saved development poses.



Each tip is capped by its own original mapping error. The separate 10 mm guard applies to the five-tip mean.

These caps preserve existing errors; they do not mean zero error or exact native geometry.

Constraint passage does not certify surface/contact fidelity. Static diagnostics only; no new evaluation episodes.