

Falta Manufatura.

17/04/2021

Nelson Nagan $\rightarrow$ Cap 7.

$$7.42 \rightarrow i_1 = i_2 = i_0 = \frac{e_{LN}}{z_1 + z_2 + z_0}$$

$$\bar{e} \approx e_{nom}; \quad z_1 = z_2 \quad i_1 = i_2 = i_0 = \frac{i_A}{3} \quad i_{tp} = i_A$$

$$\Rightarrow \frac{i_A}{3} = \frac{i_{tp}}{3} = \frac{e_{nomLN}}{2z_1 + z_0} \Rightarrow 2z_1 + z_0 = \frac{3e_{nomLN}}{i_{tp}}$$

$$z_0 = \frac{3e_{nomLN}}{i_{tp}} - 2z_1 = \frac{\sqrt{3}(\sqrt{3}e_{nomLN})}{i_{tp}} - 2z_1$$

$$z_0 = \frac{\sqrt{3}e_{nomLN}}{i_{tp}} - 2z_1$$