

Programmed dead time: 2

System clock

Ch. input

Time difference = 1

Time difference = 3

Internal counter

0

2

2

1

0

2

Set counter

Set counter

Set counter

Ch. output

Pass through hit

Inhibit hit

because counter != 0

Pass through hit

