A124_A7682M7
Firmware Release Note

LTE Module

SIMCom Wireless Solutions Limited
SIMCom Headquarters Building, Building 3, No. 289 Linhong Road, Changning District, Shanghai P.R. China
Tel: 86-21-31575100
support@simcom.com
www.simcom.com

Document Title:	A124_A7682M7 Firmware Release Note
Latest FW Version:	A124B02A7682M7
Release Date:	2024.10.11
Status:	Released

GENERAL NOTES

SIMCom OFFERS THIS INFORMATION AS A SERVICE TO ITS CUSTOMERS, TO SUPPORT APPLICATION AND ENGINEERING EFFORTS THAT USE THE PRODUCTS DESIGNED BY SIMCom. THE INFORMATION PROVIDED IS BASED UPON REQUIREMENTS SPECIFICALLY PROVIDED TO SIMCom BY THE CUSTOMERS. SIMCom HAS NOT UNDERTAKEN ANY INDEPENDENT SEARCH FOR ADDITIONAL RELEVANT INFORMATION, INCLUDING ANY INFORMATION THAT MAY BE IN THE CUSTOMER'S POSSESSION. FURTHERMORE, SYSTEM VALIDATION OF THIS PRODUCT DESIGNED BY SIMCom WITHIN A LARGER ELECTRONIC SYSTEM REMAINS THE RESPONSIBILITY OF THE CUSTOMER OR THE CUSTOMER'S SYSTEM INTEGRATOR. ALL SPECIFICATIONS SUPPLIED HEREIN ARE SUBJECT TO CHANGE.

COPYRIGHT

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION WHICH IS THE PROPERTY OF SIMCom WIRELESS SOLUTIONS LIMITED COPYING, TO OTHERS AND USING THIS DOCUMENT, ARE FORBIDDEN WITHOUT EXPRESS AUTHORITY BY SIMCom. OFFENDERS ARE LIABLE TO THE PAYMENT OF INDEMNIFICATIONS. ALL RIGHTS RESERVED BY SIMCom IN THE PROPRIETARY TECHNICAL INFORMATION, INCLUDING BUT NOT LIMITED TO REGISTRATION GRANTING OF A PATENT , A UTILITY MODEL OR DESIGN. ALL SPECIFICATION SUPPLIED HEREIN ARE SUBJECT TO CHANGE WITHOUT NOTICE AT ANY TIME.

SIMCom Wireless Solutions Limited
SIMCom Headquarters Building, Building 3, No. 289 Linhong Road, Changning District, Shanghai P.R. China
Tel: +86 21 31575100
Email: simcom@simcom.com

For more information, please visit:
https://www.simcom.com/technical_files.html

For technical support, or to report documentation errors, please visit:
https://www.simcom.com/online_questions.html or email to: support@simcom.com

Copyright © 2024 SIMCom Wireless Solutions Limited All Rights Reserved.

SIMCom Confidential

Introduction

Purpose of the document

This Release Note introduces module firmware versions and briefly describes the benefits over preceding release. Also user can find differences compared to preceding release.

New Features: It lists features or AT commands which are newly developed compared to the preceding version.

Improved Features: It lists features or parameters that have been changed or improved compared to the preceding version.

Related documents

[1] A76XX_Series_AT_Command_Manual.docx
[2] A76XX Series_TCPIP_Application Note.docx
[3] A76XX Series_HTTP(S)_Application Note.docx
[4] A76XX Series_FTP(S)_Application Note.docx
[5] A76XX Series_MQTT(S)_Application Note.docx
[6] A76XX Series_SSL_Application Note.docx
[7] A76XX Series_LBS_Application Note. docx
[8] A76XX Series_UART_Application Note.docx
[9] A76XXSeries_Sleep Mode_Application Note.docx
[10] A76XX Series_UIM HOT SWAP_Application Note.docx
[11] A76XX 系列_云平台协议_应用文档.docx
[12] A76XX Series_Audio_Application Note.docx
[13] A7600 Series_Linux_USB_Application Note.docx
[14] A76XX Series_Android_Linux_Upgrade_Manual.docx

SIMCom Confidential

Firmware Release Note

Version: A124B02A7682M7

[New Features]

[Improved Features]

1. Fixed the issue: Run “AT+CRESET AT+CFUN=1,1 AT+CFUN=6”, and the module actually crashes.
2. Optimized MQTT, configure the receiving timeout for SSL. Resolve the problem that the MQTT does not respond because the client server may not reply to SSL handshake data.
3. Other general problems solved.

SIMCom Confidential