
AC joint pass
case300 | P only
case300 | Q only
case300 | combined
case300x2 | P only
case300x2 | Q only
case300x2 | combined
case500goc | P only
case500goc | Q only
case500goc | combined
pass = 1
1.0
0.8
0.6
0.4
0.2
0.0
1.00
1.02
1.05
1.10
Absolute demand factor
AC reference
V1 native
V2 native
Frozen + PF
Frozen + PF exact
Adapted native
Adapted + PF
Adapted + PF exact
Crosses = failed finite PF iterates, not operating solutions. Shared baseline appears on each path. Blank values are N/A/UNKNOWN.