خوارزمية تشغيل قطعة

Wasdom ESP32

The first step: is to download the Arduino IDE

The second step: is to install the ESP32 cable with the computer to program it. After

that, we do the following from a file. We choose Preferences. An interface will appear

for you. Copy this link https://dl.espressif.com/dl/package_esp32_index.json and put it

in the appropriate place.

In the third step: from Tools, we choose ---> Arduino Uno board ---> Board

Administrator, type ESP32 in it, and then press install.

Fourth step: of tools we choose ---> board 'Arduino uno' --->ESP32 Arduino --->

WEMOS D1 MINI ESP32

Fifth step: of the tools we choose ---> port: "COM3" ---> COM3

Sixth step: When we want to turn on the lighting of the ESP32, we do the following

from a file we choose --> Examples ---> D1.Basics ---> Blink

Seventh step: we write the code by making a function called Void Setup and writing

Pin LED_BUILTIN as an Output using the command pinMode(LED_BUILTIN,

OUTPUT); And create another function called Void Loop, in which we write

digitalWrite (LED_BUILTIN, HiGH); to run the LED on (HIGH is the voltage level)

and delay(100); to wait for a second, digitalWrite (LED_BUILTIN, LOW); to run the

LED off making the voltage LOW and delay(100); to wait for a second