5V
GPIO19
CAP2_GPIO
I2C1_SCL
VBUS
USB_DM
UART1_RX
BOOTSEL
SWCLK
3V3
GND
GPIO20
GPIO24
CAP1_GPIO
I2C1_SDA
VSYS
USB_DP
UART1_TX
RUN\RESET
SWDIO
GND
20 19
2 1
A# B♭
G# A♭
F# G♭
C# D♭
D# E♭
F# G♭
G# A♭
A# B♭
C
B
A
G
F
E
D
C
B
A
G
F
BATT
SW1
SW2
SW3
SW4
RESET
BOOTSEL
STATUS LED
VBUS
3V3 PS
5V PS
1.8V PS
Audio Amp
COM
TP1 TERMINALS TO CONNECT EXTERNAL TOUCH PADS (EXPERIMENT BY CONNECTING TO CONDUCTIVE OBJECTS. TURN OFF POWER BEFORE CONNECTING.)