

Intel® Solid State Drive Data Center Family for PCIe* Microsoft* Windows* Driver

Release Notes

October 2017 Software Version 3.1.0.1021

Document Number: 331995-006US

Intel® Solid-State Drive Data Center Family for PCIe*



Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: http://www.intel.com/design/literature.htm

All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2016 Intel Corporation. All rights reserved.



Driver Revision History

Date	Document Version	Driver Version	Description
October	011	3.1.0.1021	New for this release: Fixed BSOD/enumeration issue during hot plug Fixed BSOD during Windows 7 OS installation
August	010	3.1.0.1009	Support for additional P4600 Intel Datacenter SSD Series skus, not currently supported in prior driver release Updates to SCSI translation for commands including Mode Select, Read Capacity, Security IN, and EUI64
May	009	3.0.0.1013	New for this release: Support for P4500 and P4600 Intel Datacenter SSD Series Hardened Driver Security Updated to NVMe Spec 1.2c Added support for Get/Set Feature Payloads when using vendor unique feature IDs Added support for the Storage Firmware Update IOCTL



	B		
Date	Document Version	Driver Version	Description
November	008	1.8.0.1011	The following was fixed in this release: Unified driver build for P3520 & other Intel Datacenter SSD Series NVMe driver no longer installs over the
			RSTe driverAdding support for the Windows 10 FWUpdate IOCTL
			Fixed Yellow Bang after surprise hot-plug that occurs in some cases
			Fixed BSOD during queue full condition with I/O
			Fixed BSOD during S3 resume that occurs in some cases
			Fixed BSOD during device power down that occurs in some cases on Windows 7
August 2016	007	1.6.0.1001_x32- x64_P3520_only	Added support for P3520 device
		1.7.0.1002	No support for P3520 device
July 2016	006	1.7.0.1002	The following was fixed in this release: BSOD during continuous reboot testing
			NVMe DVL errors blocking Windows Server 2016 Certification
June 2016		1.6.0.1001	New for this release: • P3520 Dev ID and string recognition added
April 2016	005	1.5.0.1002	New for this release: Set SCSI Mode Sense FUA bit as supported Minor performance improvement Implement SCSI Verify translation to NVMe*



Date	Document Version	Driver Version	Description
September 2015	004	1.3.0.1007	New for this release: Windows 10 Certification Single installer for both x32 and x64 based Operating Systems The following was fixed in this release: After Uninstall device shows an "unknown device," it now reports as PCIe* device. BSOD when installed on systems with 0x120 logical Cores Installer using silent install does not copy the license.
June 2015	003	1.2.0.1002	 The following was fixed in this release: Disable of NVMe Controller takes too long after S3+S4. WHCK Trim Performance Test executable encounters a divide-by-zero error and fails to execute. WHCK Rotational Rate Test Fails, Reporting 0 RPM Update Windows Driver BusType to NVMe
February 2015	002	1.1.0.1004	 The following was fixed in this release: 0x9F BSOD during S3/S4 testing BSOD due to low System Memory under 32bit Drive does not translate some SCSI commands – READ CAPACITY, REQUEST SENSE and WRITE(6) Windows Driver INF references Windows XP, there is no driver support and reference was removed
September 2014	001	1.0.0.1023	Initial release version