



CCE stages — crazing_105.jpg


00 input




01 ch0 raw intensity



02 ch1 clahe



03 ch2 hf residual



04 cce composite

