

3-Phase Induction Motor Torque-Speed Characteristic ($T = \frac{ksE_2^2R_2}{R_2^2 + (sX_2)^2}$)

Breakdown / Pull-out Torque T_{max}
(at $s_m = R_2/X_2$)

Developed Electromagnetic Torque T (Normalized)

