

ACN: 2372071

Time / Day

Date : 202606

Place

Altitude.AGL.Single Value : 150

Environment

Flight Conditions : Mixed

Weather Elements / Visibility : Rain

Light : Daylight

Aircraft

Reference : X

Aircraft Operator : Commercial Operator (UAS)

Make Model Name : Apellix Undifferentiated

Crew Size.Number Of Crew : 2

Operating Under FAR Part : Part 107

Flight Plan : None

Mission : Utility / Infrastructure

Flight Phase : Hovering (UAS)

Flight Phase : Takeoff / Launch

Flight Phase : Landing

Airspace.TFR : ZZZ

Airspace Authorization Provider (UAS) : Authorized Third Party

Operating Under Waivers / Exemptions / Authorizations (UAS) : N

Weight Category (UAS) : Small

Configuration (UAS) : Multi-Rotor

Flight Operated As (UAS) : VLOS

Flight Operated with Visual Observer (UAS) : Y

Control Mode (UAS) : Manual Control

Type (UAS) : Purchased

Number of UAS Being Controlled (UAS).Number of UAS : 1

Person

Location Of Person : Outdoor / Field Station (UAS)

Reporter Organization : Commercial Operator (UAS)

Function.Flight Crew : Remote PIC (UAS)

Function.Flight Crew : Person Manipulating Controls (UAS)

Qualification.Flight Crew : Remote Pilot (UAS)

Experience.Flight Crew.Total (UAS) : 600

Experience.Flight Crew.Last 90 Days (UAS) : 60

Experience.Flight Crew.Type (UAS) : 400

ASRS Report Number.Accession Number : 2372071

Human Factors : Training / Qualification

Human Factors : Situational Awareness

Human Factors : Human-Machine Interface

Analyst Callback : Attempted

Events

Anomaly.Airspace Violation : All Types

Anomaly.Deviation / Discrepancy - Procedural : FAR

Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy

Anomaly.Deviation / Discrepancy - Procedural : Unauthorized Flight Operations (UAS)

Detector.Person : UAS Crew

Result.General : None Reported / Taken

Assessments

Contributing Factors / Situations : Human Factors

Contributing Factors / Situations : Software and Automation

Primary Problem : Ambiguous

Narrative: 1

I frequently work in the area where a new TFR was put in place just days before. I utilized a third party app for LAANC approval because I knew I was in class C airspace with a ceiling of 400 feet. I requested

150 feet because I'm working in close proximity to 1 building and wouldn't need to climb over it. I mistakenly assumed that my request would be denied if I couldn't fly there due to other restrictions. I didn't realize that the TFR in place wouldn't block my LAANC approval. It wasn't until the next day, when I needed to request LAANC approval again and more closely read the TFR in its entirety, that I realized my error. I immediately phoned the number on the TFR and was given directions on how to properly apply for a waiver to fly in this airspace.

#### Synopsis

Part 107 UAS pilot reported flying in a TFR without authorization.