

ACN: 2372085

Time / Day

Date : 202606

Local Time Of Day : 0601-1200

Place

Locale Reference.ATC Facility : NCT.TRACON

State Reference : CA

Altitude.MSL.Single Value : 8500

Aircraft

Reference : X

ATC / Advisory.TRACON : NCT

Aircraft Operator : Air Carrier

Make Model Name : Commercial Fixed Wing

Crew Size.Number Of Crew : 2

Operating Under FAR Part : Part 121

Flight Plan : IFR

Mission : Cargo / Freight / Delivery

Flight Phase : Descent

Airspace.Class B : NCT

Airspace.Class E : NCT

Person

Location Of Person.Facility : NCT.TRACON

Reporter Organization : Government

Function.Air Traffic Control : Approach

Qualification.Air Traffic Control : Fully Certified

Experience.Air Traffic Control.Time Certified In Pos 1 (yrs) : 19

ASRS Report Number.Accession Number : 2372085

Human Factors : Human-Machine Interface

Human Factors : Workload

Events

Anomaly.ATC Issue : All Types

Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy

Anomaly.Ground Event / Encounter : Ground Equipment Issue

Detector.Person : Air Traffic Control

When Detected : In-flight

Result.Air Traffic Control : Separated Traffic

Assessments

Contributing Factors / Situations : ATC Equipment / Nav Facility / Buildings

Primary Problem : ATC Equipment / Nav Facility / Buildings

Narrative: 1

We were told by tech ops to go to ES (Emergency Service) mode for a system update. After a few minutes, I got Aircraft X IFR to ZZZ descending to 100. More than half the scopes in Area D went completely black, including mine and the SFO final controller's. Tech ops seemed to be working on the issue and for a brief time every scope went black for a few seconds before they all came back on. No issues with my aircraft, however it raises major concerns about safety of equipment; radar equipment has lately been faulty multiple times recently.

Synopsis

NCT TRACON Controller reported the radar scopes in the area went black resulting in the inability to provide radar services and an unsafe air traffic control environment.