

ACN: 2372435

Time / Day

Date : 202606

Local Time Of Day : 0001-0600

Place

Locale Reference.Airport : SFB.Airport

State Reference : FL

Altitude.MSL.Single Value : 2000

Aircraft : 1

Reference : X

ATC / Advisory.TRACON : F11

Make Model Name : Small Aircraft, Low Wing, 2 Eng, Retractable Gear

Operating Under FAR Part : Part 91

Flight Plan : IFR

Flight Phase : Cruise

Route In Use : Vectors

Aircraft : 2

Reference : Y

ATC / Advisory.TRACON : F11

Make Model Name : Small Transport, Low Wing, 2 Turboprop Eng

Flight Plan : IFR

Flight Phase : Cruise

Route In Use : Vectors

Person

Location Of Person.Facility : F11.TRACON

Reporter Organization : Government

Function.Air Traffic Control : Approach

Qualification.Air Traffic Control : Fully Certified

Experience.Air Traffic Control.Time Certified In Pos 1 (yrs) : 3

ASRS Report Number.Accession Number : 2372435

Human Factors : Communication Breakdown

Communication Breakdown.Party1 : ATC

Communication Breakdown.Party2 : Flight Crew

Events

Anomaly.ATC Issue : All Types

Anomaly.Conflict : Airborne Conflict

Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy

Anomaly.Ground Event / Encounter : Ground Equipment Issue

Detector.Person : Air Traffic Control

When Detected : In-flight

Result.Air Traffic Control : Separated Traffic

Assessments

Contributing Factors / Situations : ATC Equipment / Nav Facility / Buildings

Contributing Factors / Situations : Human Factors

Primary Problem : ATC Equipment / Nav Facility / Buildings

Narrative: 1

I was training (CPC getting re-cert time) on SFB and ORL departure satellite with my instructor. Earlier in the session our main transmitter went out on us and we switched to standbys, which have no backup frequency. As I was trying to contact Aircraft Y to climb and turn away from SFB departure corridor there was no response. I immediately switch to the orange jack back-up, still no response. At the same time Aircraft X comes off SFB on his missed approach heading southeast towards Aircraft Y. Nothing worked, mains, standbys, the emergency back-up, all were dead.

Synopsis

F11 TRACON Controller reported completely losing the main, standby, and emergency back-up frequencies while working numerous approaches and departures.