

ACN: 2372474

Time / Day

Date : 202606

Local Time Of Day : 0001-0600

Place

Locale Reference.ATC Facility : N90.TRACON

State Reference : NY

Aircraft

Reference : X

Make Model Name : No Aircraft

Person

Location Of Person.Facility : N90.TRACON

Reporter Organization : Government

Function.Air Traffic Control : Approach

Qualification.Air Traffic Control : Fully Certified

Experience.Air Traffic Control.Time Certified In Pos 1 (yrs) : 33

ASRS Report Number.Accession Number : 2372474

Events

Anomaly.ATC Issue : All Types

Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy

Anomaly.Ground Event / Encounter : Ground Equipment Issue

Detector.Person : Air Traffic Control

When Detected : In-flight

Result.General : None Reported / Taken

Assessments

Contributing Factors / Situations : ATC Equipment / Nav Facility / Buildings

Primary Problem : ATC Equipment / Nav Facility / Buildings

Narrative: 1

PHL Area C Radar went out for over couple minutes. Back up didn't work also. I just filed a report on radios not reliable and now the radar is not reliable. This is the second day in a row that the radar has gone out. The FAA forced this move in a hurry without sufficient care, planning, or thought.

Synopsis

TRACON Controller reported a radar outage for a couple of minutes and that this is the second day in a row with this outage. This resulted in an unsafe air traffic control environment.