

ACN: 2373393
Time / Day
Date : 202606
Local Time Of Day : 1201-1800
Place
Locale Reference.Airport : ZZZ.Airport
State Reference : US
Relative Position.Distance.Nautical Miles : 10
Altitude.AGL.Single Value : 100
Environment
Flight Conditions : VMC
Weather Elements / Visibility.Visibility : 10
Light : Daylight
Ceiling : CLR
Aircraft
Reference : X
Aircraft Operator : Commercial Operator (UAS)
Make Model Name : DJI Mini 5 Pro
Crew Size.Number Of Crew : 1
Operating Under FAR Part : Part 107
Mission : Photo Shoot / Video
Flight Phase : Hovering (UAS)
Airspace.TFR : ZZZ
Operating Under Waivers / Exemptions / Authorizations (UAS) : N
Weight Category (UAS) : Small
Configuration (UAS) : Multi-Rotor
Flight Operated As (UAS) : VLOS
Control Mode (UAS) : Manual Control
Flying In / Near / Over (UAS) : Crowds
Flying In / Near / Over (UAS) : People / Populated Areas
Type (UAS) : Purchased
Number of UAS Being Controlled (UAS).Number of UAS : 1
Person
Location Of Person : Outdoor / Field Station (UAS)
Reporter Organization : Commercial Operator (UAS)
Function.Flight Crew : Remote PIC (UAS)
Function.Flight Crew : Person Manipulating Controls (UAS)
Qualification.Flight Crew : Remote Pilot (UAS)
Experience.Flight Crew.Total : 100
Experience.Flight Crew.Last 90 Days (UAS) : 6
Experience.Flight Crew.Type (UAS) : 5
ASRS Report Number.Accession Number : 2373393
Human Factors : Human-Machine Interface
Human Factors : Situational Awareness
Analyst Callback : Attempted
Events
Anomaly.Airspace Violation : All Types
Anomaly.Deviation / Discrepancy - Procedural : FAR
Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy
Anomaly.Deviation / Discrepancy - Procedural : Unauthorized Flight Operations (UAS)
Detector.Person : UAS Crew
When Detected : In-flight
Result.Flight Crew : Exited Penetrated Airspace
Assessments
Contributing Factors / Situations : Human Factors
Primary Problem : Human Factors
Narrative: 1
On Day 6, I conducted a Part 107 photography mission at Location X. I had originally checked the airspace

on Day 0 and observed no permanent airspace restrictions. I did not recheck airspace status immediately prior to launch on Day 6. I launched my DJI aircraft and conducted approximately 15 minutes of photography. No geofencing or authorization warning was presented at initial startup or takeoff. After landing, I initiated a second flight. During this process, a geofencing warning appeared on the controller referencing a Temporary Flight Restriction (TFR). While hovering, I checked my airspace application and confirmed that my operating location was within the affected area of the TFR. Upon recognizing the conflict, I immediately terminated the operation and landed the aircraft.

Synopsis

Part 107 UAS pilot reported flying in an active TFR without authorization.