

ACN: 2373686

Time / Day

Date : 202604

Place

Altitude.AGL.Single Value : 0

Aircraft

Reference : X

Make Model Name : No Aircraft

Person

Location Of Person : Company

Reporter Organization : Air Carrier

Function.Dispatch : Dispatcher

Qualification.Dispatch : Dispatcher

ASRS Report Number.Accession Number : 2373686

Events

Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy

Anomaly.Ground Event / Encounter : Ground Equipment Issue

Detector.Person : Dispatch

When Detected : Routine Inspection

Result.General : None Reported / Taken

Assessments

Contributing Factors / Situations : Chart Or Publication

Contributing Factors / Situations : Software and Automation

Primary Problem : Software and Automation

Narrative: 1

Erroneous NOTAMs showing in FKYS (Flight Keys), but not in DECS (Decoding System) or Gov't NOTAM site.

Suggestions: I keep finding NOTAMs in the FKYS system that cannot be duplicated either in DECS or the FNS (Federal NOTAM System) NOTAMs page.

Synopsis

Dispatcher reported that erroneous NOTAMs are displayed in the Flight Keys software.