

ACN: 2374014  
Time / Day  
Date : 202606  
Place  
Locale Reference.ATC Facility : ZLC.ARTCC  
State Reference : UT  
Environment  
Flight Conditions : VMC  
Aircraft  
Reference : X  
ATC / Advisory.Center : ZLC  
Aircraft Operator : Air Carrier  
Make Model Name : Large Transport, Low Wing, 2 Turbojet Eng  
Crew Size.Number Of Crew : 2  
Operating Under FAR Part : Part 121  
Flight Plan : IFR  
Flight Phase : Final Approach  
Airspace.Class A : ZLC  
Component  
Aircraft Component : Electronic Flt Bag (EFB)  
Aircraft Reference : X  
Problem : Failed  
Person  
Location Of Person.Aircraft : X  
Location In Aircraft : Flight Deck  
Reporter Organization : Air Carrier  
Function.Flight Crew : Pilot Not Flying  
Function.Flight Crew : Captain  
Qualification.Flight Crew : Air Transport Pilot (ATP)  
Qualification.Flight Crew : Multiengine  
Qualification.Flight Crew : Instrument  
ASRS Report Number.Accession Number : 2374014  
Human Factors : Human-Machine Interface  
Events  
Anomaly.Aircraft Equipment Problem : Less Severe  
Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy  
Detector.Person : Flight Crew  
When Detected : In-flight  
Result.Flight Crew : Overcame Equipment Problem  
Assessments  
Contributing Factors / Situations : Chart Or Publication  
Primary Problem : Chart Or Publication  
Narrative: 1  
While at cruise from ZZZ-BZN, The FO (PF) made me aware she was going to setup for the RNAV 12 Z into BZN. When I went to change the approach in my JeppFD (Flight Deck) app, that approach wasn't available. We both verified we had the most up to date JeppFD with no updates required. I went through Mobile in Jeppesen trip kit to verify it was a legitimate legal approach for us. Once I found it, I downloaded it and used it for reference.  
Synopsis  
Air carrier Captain reported JeppFD app did not have the BZN RNAV 12 Z available in the database.