

	RS21	RS80	BEUK
entering factory cal.	paper position ..	tape reading ...	barcode (laborious) ..
ground calibration	manual corr. ..	teletype ...	not possible .
battery preparation time limits...	20 minutes .. ? ...	0 minutes ... 20 minutes ..	10 minutes .. 30 minutes ..
sonde freq. tuning	easy ...	..	..
choice Omega stations		automatic ...	manual, before launch 2) .
entering ground data	any time ...	after launch ...	before launch 3) .
correction ground data		1) .	1) .
actions during launch	radar locking .	no action ...	3) ..
data presentation during launch	PTU ... wind .	with recorder ... without rec. ..	PTU ... wind .
amount of data output	analog only .	sufficient ...	insufficient 4) .
reception stability	...	..	..

Table 8. Evaluation of operational properties; appreciation indicated by number of dots.