

Contact tip ho...	X		X		X	
Brass	24.0	142.0241.5	26.0	142.0252.5	25.0	142.0239.5
	26.0	142.0242.5 ²	28.0	142.0253.5 ³	27.0	142.0240.5 ⁴
	-	-	31.0	142.0243.5	-	-
CuCrZr	26.0	142.0274.5	29.5	142.0262.5	25.0	142.0247.5
	-	-	-	-	27.0	142.0248.5
	..	-	-	-	28.5	142.0261.5