Problem M10.1: Multithreading

Problem 10.1.A

Since there is no penalty for conditional branches, instructions take one cycle to execute unless there is a dependency problem. The following table summarizes the execution time for each instruction. From the table, the loop takes **104 cycles** to execute.

Instruction	Start Cycle	End Cycle
LW R3, 0(R1)	1	100
LW R4, 4(R1)	2	101
SEQ R3, R3, R2	101	101
BNEZ R3, End	102	102
ADD R1, R0, R4	103	103
BNEZ R1, Loop	104	104

Problem M10.1.B

If we have N threads and the first load executes in cycle 1, SEQ, which depends on the load, executes in cycle 2N + 1. To fully utilize the processor, we need to hide the 100-cycle memory latency, 2N + 1 101. The minimum number of thread needed is **50**.

Problem M10.1.C

	Throughput	Latency
Better	✓	
Same		
Worse		✓

Problem M10.1.D

In steady state, each thread can execute 6 instructions (SEQ, BNEZ, ADD, BNEZ, LW, LW). Therefore, to hide 99 cycles between the second LW and SEQ, a processor needs [99/6]+1 = 18 threads.

Problem M10.2: Multithreaded architectures

Problem M10.2.A

4, since the largest latency for any instruction is 4.

Problem M10.2.B

2/12 = 0.17 flops/cycle, on average we complete a loop every 12 cycles

Problem M10.2.C

Yes, we can hide the latency of the floating point instructions by moving the add instructions in between floating point and store instructions – we'd only need 3 threads. Moving the third load up to follow the second load would further reduce thread requirement to only 2.

Problem M10.3: Multithreading

Problem M10.3.A
Fixed Switching: Thread(s)
If we have N threads and L.D. executes in cycle 1, FADD, which depends on the load executes in cycle $2N + 1$. To fully utilize the processor, we need to hide 12-cycle memory latency, $2N + 1$ 13. The minimum number of thread needed is 6.
Data-dependent Switching: 4 Thread(s)
In steady state, each thread can execute 4 instructions (FADD, BNE, LD, ADDI). Therefore, to hide 11 cycles between ADDI and FADD, a processor needs 11/4 + 1 = 4 threads. Problem M10.3.B
Fixed Switching: 2 Thread(s)
Each FADD depends on the previous iteration's FADD. If we have N threads and the first FADD executes in cycle 1, the second FADD executes in cycle $4N + 1$. To fully utilize the processor, we need to hide 5-cycle latency, $4N + 1$ 6. The minimum number of thread needed is 2.
Data-dependent Switching: Thread(s)
In steady state, each thread can execute 4 instructions (FADD, BNE, LD, ADDI). Therefore, to hide 2 cycles between ADDI and FADD, a processor needs $2/4 + 1 = 2$ threads.

Problem M10.3.C

Consider a **Simultaneous Multithreading (SMT)** machine with limited hardware resources. **Circle** the following hardware constraints that can limit the total number of threads that the machine can support. For the item(s) that you circle, **briefly describe** the minimum requirement to support **N** threads.

(A) Number of Functional Units

Since not all the treads are executed in each cycle, the number of functional unit is not a constraint that limits the total number of threads that the machine can support.

(B) Number of Physical Registers

We need at least [N (number of architecture registers) + 1] physical registers.

(C) Data Cache Size

This is for performance reasons.

(D) Data Cache Associatively

This is for performance reasons.

Problem M10.4: Multithreading (Spring 2015 Quiz 2, Part D)

Consider the following instruction sequence.

```
addi
             r3, r0, 256
             f1, r1, #0
loop: lw
      lw
             f2, r2, #0
             f3, f1, f2
      mul
             f3, r2, #0
      SW
      addi
             r1, r1, #4
             r2, r2, #4
      addi
      addi
             r3, r3, #-1
             r3, loop
      bnez
```

Assume that memory operations take 4 cycles (i.e., if instruction I1 starts execution at cycle N, then instructions that depend on the result of I1 can only start execution at or after cycle N+4); multiply instructions take 6 cycles; and all other operations take 1 cycle. Assume the multiplier and memory are pipelined (i.e., they can start a new request every cycle). Also assume perfect branch prediction.

Problem M10.4.A

Suppose the processor performs fine-grained multithreading with fixed round-robin switching: the processor switches to the next thread every cycle, and if the instruction of the next thread is not ready, it inserts a bubble into the pipeline. What is the minimum number of threads required to fully utilize the processor every cycle while running this code?

6 threads to cover the latency between mul and sw

Problem M10.4.B

Suppose the processor performs coarse-grained multithreading, i.e. the processor only switches to another thread when there is a L2 cache miss. Will the following three metrics increase or decrease, compared to fixed round-robin switching? Use a couple of sentences to answer the following questions.

1) Compared to fixed round-robin switching, will the <u>number of threads needed for the highest</u> <u>achievable utilization</u> increase or decrease? Why?

It will decrease because the processor will switch less frequently and stall for instructions with long latency (e.g. mul).

2) Compared to fixed round-robin switching, will the <u>highest achievable pipeline utilization</u> increase or decrease? Why?

It will decrease because the processor will stall for instructions with long latency (e.g. mul) and insert bubbles into pipeline.

3) Compared to fixed round-robin switching, will **cache hit rate** increase or decrease? Why?

It will increase since there will be less threads competing the cache capacity.