

Pump handover — Line 3

PWC-AWAIT-001

Station	North — Khafji
Asset	P-331 / P-332 centrifugal pumps
Crew	Ahmed Al-Salem · Niyar Abdullah
Date	10 Sep 2026
Status	Awaiting parallel seal

Delivery checklist completed on site. Serial plates photographed.

Gasket set replaced. Alignment within 0.05 mm. No leak on first run.

Pending: recipient seal on this record. Parallel signing — others are not blocked.

Field checks


Page 2 of 4

Nameplate vs. PO	Match
Foundation bolts	Torqued
Coupling guard	Fitted
Earthing	Continuous
First-run vibration	Within band


Supervisor walked the skid with the receiving technician.
Punch items closed before this record was sent for seal.

Site photographs


Page 3 of 4

A light gray rectangular placeholder box with a thin blue border. The text "Still 1" is centered within the box.

Still 1

A light gray rectangular placeholder box with a thin blue border. The text "Still 2" is centered within the box.

Still 2

A light gray rectangular placeholder box with a thin blue border. The text "Still 3" is centered within the box.

Still 3

Three stills attached at capture time. Not a government certificate.

Hash of the sealed file is written into the company registry after the last seal.

Recipient field

Page 4 of 4

The green field on page 1 is the assigned seal spot.

Changing the studio shape updates the mark on that field before save.

Assigned seal field · page 1