
(a)
distribution
cold start
hot start
simmer
combined
Density
Thermal efficiency (fraction)
(b)
boxplot
Efficiency (fraction)
cold start
hot start
simmer
combined
(c)
violin
Efficiency (fraction)
Operational phase
(d)
phase correlation
cold
hot
simmer
combined
1.00
0.99
-0.56
-0.13
0.99
1.00
-0.59
-0.17
-0.56
-0.59
1.00
0.90
-0.13
-0.17
0.90
1.00
Pearson r