60.3.12.12 Plant SO2 Emissions [g/t clin]

Description

Plant SO_2 Emissions corresponds to the ratio of the <u>absolute SO_2 emissions</u> in relation to <u>clinker production volume</u>.

Reference to Process

This indicator refers to:


- Main cost center 'Clinker Production'
- Product sub-segment Clinker and Cement

Absolute emissions refer exclusively to main kiln stacks.

Purpose

To calculate the SO_2 emissions per unit of clinker produced.


Calculation



Plant SO2 Emissions = 'Absolute SO₂ Emissions' * 1'000'000 / 'Clinker Production Volume'

Comments and Examples

TIS data normalization code: ICS code 401+GEMITK+S02



The Plant SO_2 Emission is 110*1'000'000/400'000 = 275 [g / t clin] The abbreviation in the unit clin stands for clinker.

Reporting Requirements

This indicator is not reported in SAP FC.