

Figure 3.2 p-v-T surface and projections for a substance that contracts on freezing. (a) Three-dimensional view. (b) Phase diagram. (c) p-v diagram.




Figure A-1 Generalized compressibility chart,  $p_R \le 1.0$ . Source: E. F. Obert, Concepts of Thermodynamics, McGraw-Hill, New York, 1960.




Figure A-2 Generalized compressibility chart,  $p_R \le 10.0$ . Source: E. F. Obert, Concepts of Thermodynamics, McGraw-Hill, New York, 1960.