General test specification:

- Completely test the ALU functionality.
- Execute all lines of the ALU code.

Detailed test specification:

A. Operations & sequences

- 1. Test all operations.
- 2. Test operations with incorrect ALU operation code.
- 3. Test operations with incorrect number of data's bits.
- 4. Test operations with incorrect CRC.

B. Specific data corners

- 1. Simulate all zeros on an input for all operations.
- 2. Simulate all ones on an input for all operations.

https://github.com/nmalota/VDIC/tree/lab01/lab01