PT. REPOWER ASIA INDONESIA

FORM CECKLIST MEKANIKAL - ELEKTRIKAL

TGL/BLN/THN: 28 / 5 / 2020

NO	PEKERJAAN M & E	STATUS			PERMASALAHAN	TGL	KETERANGAI
	PENELOZAMI WI OLE	В	С	R	PERMAJAEATIAN	PERBAIKAN	TE LETTER TO A
I AREA							
The second name of the second	pompa air	V			tolover ou		7,407
2 Lampu	u pos satpam	V					
3 Lampu	u parkir		×				
4 Lampu	u teras	V					
5 Outdo	or unit AC	~					
6 Kran		V					
II LANTA	AI SATU						
1 Panel	Meter (Volt + Ampere)	V			TR: 380V ST: 380V RS: 380V		
2 MCB		V			,		
3 Lampu	u down light	V			Lample max1 2 pcs		
4 Stop k		V					2201
5 Saklar		V					
6 Indoo	r unit AC	V			set 04 10.00		
7 Closet		U			1		
8 Wasta		V					
9 Kran		V					
10 Plumb	oing	V					
141							
III LANTA	AI DUA						
1 Panel		~					-
2 MCB		1					
	u down light	L			Lampu mode: Y pos		
4 Stop k		V					2200
5 Saklar							0000
-	r unit AC	V			sex off 18.00		
7 Closet		V			10. 9/ /0 00		
8 Wasta							
	ilei	V					
9 Kran	to a	V					
10 Plumb		~					-
11 Outdo		-					
IV LANTA	ALTIGA						
1 Panel		1	11				
2 MCB	1 0 1	-		1	12.70		
the Real Property lies, Name of Street, or other Designation of the last of th	u down light	V			Towbre was: 3 ber		
4 Stop k		V					
5 Saklar		V					
The same of the sa	r unit AC	V			set off 10.00.		
7 Closet		V					
8 Wasta	ifel	U					
9 Kran		V					1000 1000
10 Plumb		V					
11 Outdo	or unit	V				1227 5 45	

	LANTAI EMPAT			
	1 Panel			
1	MCB	-		
17	Lampu down light		Lampo max; 2 pcs	
4	Stop kontak		zon france pu	220V
5	Saklar	U		2000
6	Indoor unit AC		NO 01 11 60	
7	Closet	V	Set 8ff 18.00	
8	Wastafel			
9	Kran	V		
10	Plumbing			
	Outdoor unit	V		
VI	LANTAI LIMA			
1	Panel	~		
2	MCB			
1/3	Lampu down light		Lampe max: 2 po	
	Stop kontak			220V
5	Saklar			
6	Indoor unit AC		Ser 8ft 10.00	
	Closet			
-	Wastafel			
9	Kran	V		
10	Plumbing			
	Outdoor unit			

KET	TED	ANI	GA	NI-
IV.		HIN	UF	WIN.

- Pendsongan Lampu gantung 2t 5 (2 Unit) - Perubahan tata Ruang Presours.

B: Baik

C: Ada/Tidak

R: Rusak

Dibuat

Diketahui

(Wiyono)

Dipindai dengan CamScanner