

Advanced Surgical Robots Homework 2

Problem 1:











Problem 2:



	q1	q2	q3	q4	q 5	q6
X (mm)	0	1.1	4.2	3.9	0	0
Y (mm)	0	0	0	1.4	4.2	4.2
Z (mm)	8	7.7	5	5	5	10



Problem 3:

None of the q vectors cause strain to exceed maximum recoverable strain. A delta L of 2.65mm cause strain to exceed NiTi maximum recoverable strain.

Problem 4:

