Égère state Cmde cone stop machine init Cmde aero stop Led alive 0.25s cone closed cone open cone Cmde cone open Time-out = 5sopening cone_open Cmde aero open aero Cmde cone stop Cmde cone stop opening parachute Cmde aero stop Time-out = 5s Led open 1s Led alive 0.5s time out cone_open Cmde cone stop Cmde aero stop aero braking Cmde aero open open Time-out = 0.1stime_out time out time out cone_closed Cmde cone open cone Time-out = 5s cone Cmde aero stop open closing Time-out = 0.1sLed open 0.1s time out time_out Cmde cone close cone Cmde cone close flight Cmde aero close Time-out = 1sclosed Time-out = flight-time Led alive 0.1s Led alive 0.1s take_off time_out Cmde cone stop waiting Led alive 1s