NOAA Ship THOMAS JEFFERSON Procedure Document

Procedure:
POS M/V GAMS Calibration
Creation Date:
04/13/2022
Revision Date:
Software used:
MV-POSView 10.x
Procedure Number:
TBD
Approved:
TBD

1. Overview and Scope

This brief write-up is a simplified procedure for conducting a GAMS calibration on any of the three POS M/V 320 v5's aboard *Thomas Jefferson*. For a more detailed explanation consult the latest manual available.


2. Procedure Inputs and Outputs

Inputs:

Outputs:

3. Procedure

1. Ensure that the correct settings are in place for normal POS operations including: Correct lever-arm offsets are entered- check with CHST/OPS Receiving differential correctors- Nav. Status should say Pri. DGPS




2. Open the Excel POS MV Cal Report found here:

"K:\Standard_Operating_Procedures\05_HSRR\Reference


Files\Vessel_POS_MV_Cal_Report_20YY.xls" You can start filling out the information and populating screen shots before starting the calibration.

- 3. Go to View > GAMS Solution. Check to ensure:
 - GAMS Heading Accuracy is below 0.5
 - PDOP is below 3.0
 - SV's in Solution is >5

Keep this window open during the calibration procedure.



4. Press the Connect button to connect to POS . Navigate to Settings > Installation > User Accuracy and ensure values are set as seen below.



- 5. When ready to perform the calibration, press the Stand By button . This will zero out all of the attitude readings and turn the Accuracy lamps to red.
- 6. Press the NAV button to the right of the Stand By button . This will reset the status of the attitude sensors and the Accuracy lamps will start turning back to green. Some may remain red- this is ok.
- 7. Once the above requirements are met, navigate to Settings > GAMS Calibration Control > Start

8. When the GAMS status displays CAL Requested, begin driving aggressive S and figure 8 turns at high speed. Keep an eye on the GAMS status during this time.



- 9. When the Gams status displays CAL in Progress, drive a straight line until the GAMS status changes to CAL Complete. You will see a progress bar at the bottom of the GAMS Solution window that will show the progress of the calibration and will show 100% when finished.
- 10. Complete the remaining sections of the POS MV Cal Report. Compare the initial GAMS Baseline Vector values to the ones achieved after calibration. Consult with CHST/OPS if the values differ by a few centimeters or more. If instructed, perform another calibration.
- 11. If the baseline vector values are close to the initial values, or if CHST/OPS deem the final values appropriate, close all windows and click the disconnect button. **Click OK to save changes**.



12. Click File > Save POS Config to save a new configuration file after calibration is complete. Consult CHST/OPS for file location and naming convention and note the file name in the calibration report.

4. References