


123 Main Street Golden CO 80401

SCORE TODAY

8

YEAR BUILT: 1961 CONDITIONED FLOOR AREA: 2,400 FT²

Average Home Score



The U.S. Department of Energy's Home Energy Score assesses the energy efficiency of a home based on its structure and heating, cooling, and hot water systems. For more information visit HomeEnergyScore.gov.



123 Main Street Golden CO 80401 SCORE

8

Home Facts

The Home Energy Score's Home Facts includes details about the home's current structure, systems, and estimated energy use. For more information about how the score is calculated, visit our website at HomeEnergyScore.gov.

About This Home

ASSESSMENT

Type Initial

Assessor name TST-Pivotal

Scoring tool version

HOME CONSTRUCTION

Year built 1961

Number of bedrooms 4 Stories above ground level 1

Interior floor-to-ceiling height 7 ft

Conditioned floor area 2,400 ft²

Direction faced by front of house North

House Shape Rectangle

Air leakage rate 1204 CFM50



Estimated Annual Energy Use

ENERGY BY TYPE

Total 135 MBtus

Score basis 63 MBtus

Energy use per square foot 34 kBtu / ft²

Electricity 8,302 kWh Natural gas 541 therms

ENERGY COST ESTIMATES

Total annual energy costs \$1,239 Energy cost per square foot \$0.52 ft²

> Electricity \$0.119 / kWh Natural gas \$0.782 / therm

DEFINITIONS & CONVERSIONS

MBtu Million British thermal units; generic energy unit

kBtu Thousand British thermal units; generic energy unit

kWh Kilowatt-hour; electricity unit Therm 100,000 Btu; heat energy unit

Electricity conversion 1 MBTU = 293 kWh

Heat conversion 1 MBTU = 10 therms







123 Main Street Golden CO 80401 SCORE

8

Home Facts

The Home Energy Score's Home Facts includes details about the home's current structure, systems, and estimated energy use. For more information about how the score is calculated, visit our website at HomeEnergyScore.gov.

Roof / Attic

ROOF / ATTIC 1

Attic floor area 1,200 ft²

Roof construction Standard / Composition Shingles or Metal / R-0

Roof color Medium

Attic floor insulation R-49

Foundation

FOUNDATION / FLOOR 1

Floor area 1,200 ft²

Foundation type Conditioned basement / R-0

Foundation walls insulation R-0

Walls



Front Wood frame / Brick veneer R-11
Back Wood frame / Brick veneer R-11
Right Wood frame / Brick veneer R-11
Left Wood frame / Brick veneer R-11



ASSESSMENT: Initial | Dec 02, 2014 | ID# 225875



123 Main Street Golden CO 80401 SCORE

8

Home Facts

The Home Energy Score's Home Facts includes details about the home's current structure, systems, and estimated energy use. For more information about how the score is calculated, visit our website at HomeEnergyScore.gov.

Windows & Skylights

WINDOW AREA

Front 1 ft²
Back 3 ft²
Right 4 ft²
Left 2 ft²

WINDOW CONSTRUCTION PANES FRAME GLAZING SOLAR SCREEN

U-Value: 1 / SHGC: 0.75 Front No Wood or vinyl Clear Back Double No Right Double Wood or vinyl Clear No Wood or vinyl Double Clear No Left

SKYLIGHTS ROOF / ATTIC 1

Present? Yes

Area 11 ft²

Type Double Aluminum with Thermal Break Clear No



123 Main Street Golden CO 80401 SCORE TODAY 8

Home Facts

The Home Energy Score's Home Facts includes details about the home's current structure, systems, and estimated energy use. For more information about how the score is calculated, visit our website at HomeEnergyScore.gov.

Systems

HVAC SYSTEM 1

Percent conditioned area served 100%

Heating type Central gas furnace

Heating efficiency value 95% AFUE

Cooling type Central air conditioner

Cooling efficiency value 13 SEER

<u>DUCT SYSTEM 1 INSULATED? SEALED? PERCENT OF DUCTS IN THIS LOCATION</u>

Conditioned space No No 100%

HOT WATER

System type Natural gas storage

Installation year 2010





123 Main Street Golden CO 80401 SCORE TODAY 8

Recommendations

The Home Energy Score's Recommendations show how to improve the energy efficiency of the home to achieve a higher score and save money. When making energy related upgrades, homeowners should consult with a certified energy professional or other technically qualified contractor to ensure proper sizing, installation, safety, and adherence to code. Learn more at HomeEnergyScore.gov.

Recommended Improvements



<u>REPAIR NOW</u>. The Home Energy Score model did not identify any cost-effective repairs. Please ask your assessor for more information.

REPLACE LATER. These improvements will help you save energy when it's time to replace or upgrade.

Water heater: Pick one with an ENERGY STAR label to save \$30 / year

Comments



