## SensorManager

+ calibrateSCD30()

+ checkAndCalibrateSCD30()

+ isDataAvailable() + resetCalibrationFlag()

+ getCO2()

+ getHumidity()

+ getPressure()

+ getTemperatureBMP()

+ getTemperatureSCD()

+ initializeSensors()