SensorManager + calibrateSCD30() + checkAndCalibrateSCD30() + getCO2()

+ getTemperatureBMP()
+ getTemperatureSCD()
+ initializeSensors()
+ isDataAvailable()
+ resetCalibrationFlag()

+ getHumidity()
+ getPressure()