



LAB TASK 1

1.2



This behavior of steady hover is evident by these plots of the time history of various measurements about the state of the quadrotor. All elements are flat because they are not changing over time but rather hovering and staying in one place at equilibrium.

1.3 A



1.3 B

