

R

B17 Events During High-Ambient Operation

Fleet Reliability Engineering Bulletin

BULLETIN	FRE-2026-017
VERSION	1.3
EFFECTIVE	July 10, 2026
STATUS	Approved — Synthetic
AUDIENCE	Reliability engineering

Access scope: Engineering Restricted. Field technicians do not receive this source unless their assigned principal is granted the scope.

SYNTHETIC RESTRICTED BULLETIN · NOT FOR FIELD USE

2. Fleet Pattern and Engineering Guidance

Synthetic fleet review found that B17 frequency increased when ambient temperature exceeded 35 °C and cooling-path restriction was also present. Ambient temperature alone was not a sufficient predictor.

2.1 Observed pattern

CONDITION	SYNTHETIC OBSERVATION	INTERPRETATION
Ambient ≤ 35 °C	Low B17 frequency	Normal thermal margin in reviewed sample
Ambient > 35 °C, clear cooling path	Occasional short derating	High ambient reduces margin but does not prove a defect
Ambient > 35 °C plus restricted airflow	Repeated or longer B17 events	Prioritize cooling-path inspection

2.2 Engineering recommendations

- Treat 35 °C as a fleet-analysis context threshold, not an OEM trip or derating setpoint.
- Do not infer fan failure or contamination from temperature and weather data alone.
- For repeated B17 events, compare affected units with same-model peers and review inspection results.
- Retain the exact metric window, document versions, and field disposition with each diagnostic run.

For the Manatee example: A 36.8 °C ambient peak provides relevant context, while the 78.4 °C controller peak versus the 75 °C OEM threshold establishes the deterministic exceedance.