

BMS Circuit Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Circuit Fault	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	Battery circuit fault: the hardware of the battery has problems

Suggestion

1.For T58 batteries paired with the BMS parallel box G2, check if the master-slave communication wires are crossed.

2.If paired with the BMS Parallel Box G1,provide the completed troubleshooting results to SolaX technical support team through video or images.Including but not limited to:

- 1) SN number of the inverter.
- 2)The photo of the BMS Parallel box.