

BMS Current Sensor Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Current Sensor Fault	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	Battery current sensor failure.

Suggestion

1. Upgrade all batteries to the latest firmware. If the error persists, connect each battery to the system individually to identify the faulty battery.
2. If the issue remains, provide the completed troubleshooting results to SolaX technical support team through video or images. Including but not limited to:
 - 1) SN number of the inverter.
 - 2) SN number of the faulty battery.