

BMS Over Voltage

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Over Voltage	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	Battery cell overvoltage fault: The voltage of the battery cell exceeds 3.68V

Suggestion

1. Upgrade the inverter firmware and observe for 2-3 days. If the error persists, use the T-BAT-Charger to check the detailed cell voltage information of each battery and provide to the SolaX technical support team for further analysis. If the T-BAT-Charger is unavailable, provide the inverter's SN number to the SolaX technical support team for further analysis.