

EPS Relay Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
EPS Relay Fault	General	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	EPS relay malfunction
2	Relay self-check failed

Suggestion

- 1.Try multiple grid-to-off-grid switches.
- 2.If the fault persists, update the firmware to the latest version. If the issue remains, provide the inverter's SN number to the SolaX technical support team for further analysis.