

Grid Relay Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
Grid Relay Fault	General	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	Grid relay malfunction
2	Relay self-check failed

Suggestion

1. Check if the N line is properly connected.
2. Restart the inverter multiple times to check if the error occurs.
3. Upgrade the firmware to latest version.
4. If the issue remains, provide the inverter's SN number to the SolaX technical support team for further analysis.