

Mgr EEPROM Error

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
Mgr EEPROM Error	General	Communication alarm

Possible Cause

Cause ID	Possible Cause
1	Mgr EEPROM Failure
2	ARM EEPROM read/write failure

Suggestion

1. Upgrade the firmware to the latest version and restart the inverter.
2. If the issue remains, provide the inverter's SN number to the SolaX technical support team for further analysis.