

RC Over Current Protection Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
RC Over Current Protection Fault	General Alarm	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	Residual current over-current Fault: On-grid residual current exceeds the threshold set by the safety code.

Suggestion

- 1.Check the error frequency. If the error occurs occasionally, inspect the PE wire to ensure it is properly connected and not damaged.
- 2.If the issue remains, provide the inverter's SN number to the SolaX technical support team for further analysis.