

RCD Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
RCD Fault	General	Inverter alarm

Possible Cause

Cause ID	Possible Cause
1	RCD device malfunction
2	Leakage current detection circuit self-check failed

Suggestion

1. Check the error frequency. If the error occurs occasionally, upgrade the firmware and restart the inverter. If the error persists, provide the inverter's SN number to the SolaX technical support team for further analysis.