Operation	Result	Op Code
FLG	FLAG	0000
ADD	C=A+B	0001+0
SUB	C=A-B	0001+1
INC	C=A+1	0001+0, B=0001
DEC	C=A-1	0001+1, B=0001
SHL	C=A<<1	0010
NOT	C=!A	0011
AND	C=A&B	0100
ORR	C=A B	0101
XOR	C=A^B	0110
SET	r=A	0111
SRT	r1=r2	1000
JMP	jump to address in instruction reg	1001
GOF	goto adress in instruction reg IF FLAG BIT = 1	1010
GOT	goto adress in instruction reg	1011
RET	return to jmp loc	1100
LBL	set label	1101
BPZ	C = A&(1< <b)< td=""><td>1110</td></b)<>	1110
		1111
FLAG:	E,C,N,G	
	E = A==B	
	C = Cout, Bout	
	N = A==0	
	G = A>B	