

MRT-1094 (05-26-16) "Dust Plate & Dust Cap Installation"

Place the dust plate into the solder pot as seen. P/N 10000182.
NOTE: The orientation of the dust plate as it is laid into the solder pot!





2. Place the **dust cap** over the riser onto the plate as shown. P/N 10000183.





Customer Service Nordson SELECT, Inc. 22425 East Appleway Ave Suite 1

Liberty Lake, WA 99019 Office: +1.509.924.4898 Fax: +1.509.533.1299