


DX-70T External Amplifier Relay Modification



Locate and cut or remove R534

NOTE Any damage done while performing this modification will void any and all warranties.