REP103 Standard Units of Measure | & Coordinate Conventions

=> We have chosen to standardize on SI Units.

* Coordinate frame Conventions

(1) All systems are sight harded.

Si.e. they comply with sight hard thumbs
sincle

2) An oraliand to a body the standard is:

3 An the case of Camenas, there is often a Second frame defined with a "-optical" suffix.

This uses a slightly different Convention:

* Rotation Reposes antation

-> There are many ways to oraprosent oratations.

=> The profesed order is!

- 1 Quaternion
- 1 Rotation metrix
- @ fixed axis only, pitch, you about X, Y, Z oxes onespectively,
- 9 Eulen angles you, pitch, and soll about Z,Y, X axies snospectively.

Countercluckwise motorion => tre

* Covariance Representation

- 1 linear Ly 3x3 grow major motrix in X, Y, Z onder
- D Angelan Ly 3x3 grow major modrix about X, Y, Z order with fixed axies.
- 3 Six Dimensiond

 Row-major or eposesentation of the 6x8

 Covariance medoix.

 It Am corder, the parameters are:

 X, Y, Z, ordetion about X axis,

 ordetion about Yaxis, rotation about Zaxis