




- AGROTEKNO
- BONDOWOSO
- F.TEKNIK
- FAPERTA
- FARMASI
- FATETA
- FKEP
- FKG
- FKIP
- FKM
- FKU
- FMIPA
- IsDB-FTP-FMIPA
- ISDB-TEKNIK
- IsDB-TOA-Selatan
- IsDB-TOA-Utara
- JUBUNG
- Masjid Al-Hikmah
- MOBILE
- Nakula Sadewa
- RS SOEBANDI
- Stock AP
- TEKNIK PATRANG
- UMC
- Unit Kerja
- UPT BAHASA
- UPTTIK
- Sites overview


## Username


## Dipta


• Edit account Logout


F














Statistics




Insights



**Events** 



Alerts



## Settings

- Site
- · Wireless Networks
- Networks
- Routing & Firewall
- Threat Management
- DPI
- Guest Control
- Profiles
- Services
- Admins
- User Groups
- Network Application
- User Interface
- Remote Access

All (30)

Wireless (29)


Wired (1)


LTS (0)

**EOL** (4)

Filter by: All
Device type
All
Wireless
Wireless
Wired
Support type
LTS
Co
EOL

Search or select tag





Device Name	MAC Address	IP Address	Status	Experience	Model	Uptime	
US-8-150W:f86f	18:e8:29:5f:f8:6f	10.126.1.109	Connected	100%	1 IS-X-	49d 8h 29m 11s	Locate  Restart  Upgrade
FKM-DepanServerLama	04:18:d6:c0:08:f4	10.126.1.115	Connected Eol	No clients	UAP- AC- Pro	16d 11h 43s	Locate Restart
FKM-GazeboDepan	f0:9f:c2:73:ec:fb	10.126.1.96	Connected	61%		1d 8h 53m 29s	Locate  Restart  Upgrade
FKM-GdDekanat-lobbybarat	e0:63:da:33:74:0c	10.126.1.126	Connected	No clients	AC-	1d 8h 52m 44s	Locate  Restart  Upgrade

1-30 of 30 devices

Rows per page 50 ▶

Device Name	MAC Address	IP Address	Status	Experience	Model	Uptime	
FKM-GdDekanat- LobbyTimur	74:83:c2:cc:ec:1e	10.126.1.84	Connected	No clients	UAP- AC- Pro	1d 8h 53m 18s	Locate  Restart  Upgrade
FKM-GdDekanat-Lt2	04:18:d6:c0:08:91	10.126.1.110	Connected Eol	No clients	UAP- AC- Pro	49d 9h 20m 5s	Locate Restart Upgrade
FKM-GdDekanat-Lt2- R.pertemuan	f0:9f:c2:76:16:e0	10.126.1.112	Connected	No clients	UAP- AC- Pro	34d 6h 11m 36s	Locate Restart Upgrade
FKM-Gedung Lama RK-1	f0:9f:c2:73:e6:36	10.126.1.102	Connected	95%	UAP- AC- Pro	16d 11h 16s	Locate Restart Upgrade
FKM- GedungAulaBelakang(HD)	24:5a:4c:95:53:b0	10.126.1.86	Connected 100 FDX	96%	UAP- AC-HD	1d 20h 23m 33s	Locate Restart Upgrade
FKM-GedungLama- RK3(milik-sendiri)	78:8a:20:d9:94:1e	10.126.1.100	Connected	97%	UAP- AC-LR	5d 4h 15m 50s	Locate Restart Upgrade
FKM-GedungLama- RK4(milik-sendiri)	78:8a:20:d9:94:4e	10.126.1.101	Connected	85%	UAP- AC-LR	16d 11h 47s	Locate Restart Upgrade
FKM-GedungLama-RK5	f0:9f:c2:73:e2:df	10.126.1.107	Connected	93%	UAP- AC- Pro	16d 11h 1m 21s	Locate Restart Upgrade
FKM-Kantin(milik-sendiri)	e0:63:da:33:71:89	10.126.1.105	Connected 100 FDX	100%	UAP- AC- Pro	1d 20h 22m 21s	Locate Restart Upgrade
FKM-KesehatanLingkungan- LT3	18:e8:29:9c:a7:2b	10.126.1.95	Connected	No clients	UAP- AC- Lite	49d 9h 18m 12s	Locate Restart Upgrade
FKM-LAB-A-Barat	74:83:c2:2c:a0:a7	10.126.1.106	Connected	89%	UAP- AC- Pro	49d 8h 27m 39s	Locate Restart Upgrade
FKM-LabB-Timur	74:83:c2:2c:92:6e	10.126.1.98	Connected	80%	UAP- AC- Pro	49d 8h 26m 53s	Locate Restart Upgrade
FKM-Labkom(milik-sendiri)	e0:63:da:33:72:b4	10.126.1.97	Connected	99%	UAP- AC- Pro	16d 11h 26s	Locate Restart Upgrade
FKM-LabTengah	74:83:c2:2c:9f:5a	10.126.1.103	Connected	No clients	UAP- AC- Pro	45d 9h 26m 12s	Locate Restart Upgrade
FKM-PromosiKesehatan- LT3	18:e8:29:9c:85:04	10.126.1.123	Connected	60%	UAP- AC- Lite	49d 9h 18m 31s	Locate Restart Upgrade
FKM-R.sidang-Lt2	74:83:c2:2c:9c:5c	10.126.1.120	Connected	No clients	UAP- AC- Pro	49d 9h 18m 56s	Locate Restart Upgrade
FKM-RK2	f0:9f:c2:76:05:00	10.126.1.104	Connected	100%	UAP- AC-	16d 11h 50s	Locate Restart
1-30 of 30 devices					Pro		

1-30 of 30 devices

Rows per page

<b>Device Name</b>	MAC Address	IP Address	Status	Experience	Model	Uptime	
							Upgrade
					UAP-	9d 5h	Locate
FKM-RK6(milik-sendiri)	74:83:c2:2c:9c:dd	10.126.1.125	Connected	No clients	AC- Pro	35m 47s	Restart
							Upgrade
FKM-RK7(milik-sendiri ) ialur	74:83:c2:2c:9f:86	10.126.1.117		75%	UAP- AC- Pro	9d 5h 35m 36s	Locate
di ganti LABKOM							Restart
							Upgrade
FKM-RK8	dc:9f:db:f6:95:70	10.126.1.119	Connected Eol	95%	UAP	16d 11h 1m	Locate Restart
			Loi			1d 20h	Restait
FKM-UKM-Belakang	44:d9:e7:c6:46:95	10.126.1.85	Connected	91%	UAP-	22m	Locate
J			Eol		LR	35s	Restart
EIGH EDIDADIOO I IA		40 400 4 400	<b>-</b>		UAP-		
FKM-EPID&BIOS-Lt3	18:e8:29:9c:a6:48	10.126.1.122	Disconnected	No clients	AC- Lite		
					UAP-		
FKM-GedungLama-RK10	f0:9f:c2:76:06:47	10.10.112.113	Disconnected	No clients	AC-		
					Pro		
EKM CiziMagyarakat Lt2	18:e8:29:9c:a7:2e	10 106 1 110	Disconnected	No oliente	UAP- AC-		
FKM-GiziMasyarakat-Lt3	10.60.29.90.87.26	10.120.1.110	Disconnected	NO CHERIS	Lite		
FKM-RK9	f0:9f:c2:b4:67:dd	10.10.112.81	Disconnected	No clients	UAPv2		
FKM KebijakanMasyarakat-					UAP-		
Lt3	18:e8:29:9c:a7:4a	10.126.1.113	Disconnected	No clients	AC-		
-					Lite		

1-30 of 30 devices

Rows per page