## Steps to setup ESP32 in computer:

- 1- Plug the ESP32 to your PC or laptop by using micro cable.
- 2- Go to Tools > Board > Boards Manager > from the search bar write "esp32" > click on install.
- 3- Go to Tools > Board > select the name of your ESP32 board.
- 4- Go to Tools > Port and select a COM port available.
- 5- write the following code in arduion editor:

```
void setup() {
  pinMode(LED_BUILTIN, OUTPUT);
}

void loop() {
  digitalWrite(LED_BUILTIN, HIGH);
  delay(1000);
  digitalWrite(LED_BUILTIN, LOW);
  delay(1000);
}
```

6- Press the upload button.